

PRESSURE CUFF PU TRANSPARENT "CLEAR FUSE"

Ref. M31000



30/07/2025 02:42:17 - For information purposes only, can be subject to change

GSH | 30 rue Jean de Guiramand
13290 Aix-en-Provence | France

www.gsh-med.fr

+33(0)4 42 90 31 31

info@gsh-med.fr

PRESSURE CUFF PU TRANSPARENT "CLEAR FUSE"

Ref. M31000

CLEAR FUSE, the transparent press stud cuff made in France!

Description

Pressure cuffs are medical devices designed for use in operating theatres, intensive care units and emergency transport vehicles. They are used to manually accelerate the infusion of blood and solutions when gravity is not sufficient to achieve the desired flow rates.

The CLEAR FUSE pressure cuff is compatible with all IV and blood bags, and is available in 3 sizes: 500cc (M30500) , 1000cc (M31000), 3000cc (M34000).

Optimised monitoring and reliability

Reusable and easy to clean/disinfect

Extremely easy to use. The bag fits into the open cuff on a flat surface, not when hanging from the serum stand.

Visualisation of the solution bag thanks to the PU material that rolls it up.

Pressure range from 0 to 300mmHg in 10mmHg increments.

Pressure gauge accuracy ± 3 mmHg

Red zone on dial at 300mmHg to prevent overpressure

Controlled decompression with a simple tap

Durable, as it is made from TPU membrane welded by high-frequency welding.

All our pressure cuffs are manufactured in our Castelculier plant near Agen.

 30/07/2025 02:42:17 - For information purposes only, can be subject to change

GSH | 30 rue Jean de Guiramand

13290 Aix-en-Provence | France

 www.gsh-med.fr

 +33(0)4 42 90 31 31

 info@gsh-med.fr

PRESSURE CUFF PU TRANSPARENT "CLEAR FUSE"

Ref. M31000

Features

| | | | |
|-----------------------------|---------------|---------------------------|---------|
| CE Marking | CE | Medical device | Class I |
| Bar code | 3700468203940 | HS Code | 981090 |
| Warranty (months) | 24 | Country | France |
| DIMENSIONS AND WEIGHT | | | |
| Packed unit / Width (cm) | nc | Packed unit / Height (cm) | nc |
| Packed unit / Length (cm) | nc | Packed unit / Weight | nc |
| Bare Unit / Weight (kg) | 400 | | |
| SPECIFIC STORAGE CONDITIONS | | | |
| Minimum temperature | -10 | Max temperature | 40 |
| Minimum humidity | 30 | Maximum humidity | 40 |
| OTHER FEATURES | | | |

30/07/2025 02:42:17 - For information purposes only, can be subject to change

GSH | 30 rue Jean de Guiramand
13290 Aix-en-Provence | France
www.gsh-med.fr

+33(0)4 42 90 31 31
info@gsh-med.fr